

Palintest

Water Analysis Technologies

Sulfite

Photometric test for Sulfite in treated water

COLOUR CHANGE

Purple to Colourless

RANGE:

0 - 500 mg/L Na_2SO_3

TECHNICAL RESOURCE:

Sulfite Test Method, Technical Information

01




Fill to the 10 mL line with sample.

02




Use this to "blank" the instrument. Place in cell holder and press Blank.

03




Prepare sample by adding a Sulfitest No1 tablet and crush and stir.

04



Then, add a Sulfitest No2 tablet and crush and stir.

05



Place in the cell holder and press Measure.

06



Allow timer to count down 2 minutes. The concentration of Sulfite will then be displayed.